

Description of Repairs (invoice)	Labor	Time	Charges
REPLACE RADIADOR	120	1	PARTS:
REPLACE WATER PUM	90	1	\$ 0
			LABOR:
			\$ 0
			SUBLET/OTHER:
			\$ 0
			SUPPLIES:
			\$ 0
			FEES:
			\$ 0
			SUB-TOTAL:
			\$ 382
			TAX:
			\$ 27
This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal. *FS403.718 mandates a \$1.00 fee for each new tire sold in the State of Florida. ***FS403.7185 mandates a \$1.50 fee for each new or remanufactured battery sold in the State of Florida.			TOTAL: \$ 408.74