

<p>PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:</p> <p>I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED \$100.</p> <p><input type="checkbox"/> I REQUEST A WRITTEN ESTIMATE.</p> <p><input type="checkbox"/> I DO NOT REQUEST A WRITTEN ESTIMATE.</p> <p>X I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$0.00. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.</p> <p>SIGNED: _____ DATE: 02/09/2019</p>					<div><div><div>GUANE GAS STATION</div><div>GENERAL MECHANIC</div><div>1201 NW 7 ST, MIAMI, FL, 33125</div><div>Phs: 786-253-0646</div><div>MVR: 07110 MV-47286 INVOICE: 3283</div></div></div>				month/mile warranty on all parts.					
									Intended Payment Method:					
									cash					
									Date: 2/6/2019 Time: 1:45 pm					
										Name: LEONALDO VALDES				Proposed Completion Date:
					Address:				Home Ph:					
					City:		State: FL		Zip:		Work Ph:			
					Other Authorized Person:				Phone:					
					Year/Make: 2001 FORD			Model: F150		Tag:		Miles In: 0		
					VIN#:						Miles Out: 0			
					Save Old Parts: no (Core may apply)									
<div><div>Qty</div><div>Part</div><div>Description</div><div>Price</div><div>Warranty</div></div> <div><div>2</div><div>RK8726</div><div>COMTROL ARM</div><div>62.36</div><div>2 year</div></div> <div><div>1</div><div>K8700</div><div>IDLER ARM</div><div>56.13</div><div>2 year</div></div> <div><div>2</div><div>DWES3365</div><div>TIE ROD END</div><div>23.75</div><div>1 year</div></div> <div><div>2</div><div>DWE3366</div><div>TIE ROD END</div><div>24.25</div><div>1 year</div></div> <div><div>2</div><div>A18</div><div>BEARING</div><div>16.00</div><div>1 year</div></div> <div><div>1</div><div>HY145310</div><div>BRK ROTOR</div><div>47.00</div><div>1 year</div></div> <div><div>1</div><div>GNAD679</div><div>BRK SET PAD</div><div>30.00</div><div>1 year</div></div> <div><div>1</div><div>DWK800</div><div>BALL JOINT</div><div>38.76</div><div>1 year</div></div> <div><div>2</div><div>SP405</div><div>SPARK PLUG</div><div>6.27</div><div>1 year</div></div> <div><div></div><div></div><div></div><div></div><div></div></div> <div><div></div><div></div><div></div><div></div><div></div></div> <div><div></div><div></div><div></div><div></div><div></div></div> <div><div></div><div></div><div></div><div></div><div></div></div> <div><div></div><div></div><div></div><div></div><div></div></div> <div><div></div><div></div><div></div><div></div><div></div></div> <div><div></div><div></div><div></div><div></div><div></div></div> <div><div></div><div></div><div></div><div></div><div></div></div> <div><div></div><div></div><div></div><div></div><div></div></div>														

Complaint/Problem:

Labor charges based on:

hourly rate

Estimate/diagnostic fee:

/ Or hourly at \$ 0.00 Per hour

Estimate good for 30 days. Not responsible for damage caused by theft, fire or acts of nature. I hereby authorize the above repairs, including sublet work, along with the necessary materials. You and your employees may operate my vehicle for the purpose of testing, inspection and delivery at my risk. If I cancel repairs prior to their completion for any reason, a tear down and reassembly fee of \$ 0 will be applied.

SIGNED: _____ DATE: 02/09/2019

**This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal.

***FS403.718 mandates a \$1.00 fee for each new tire sold in the Sate of Florida. ***FS403.7185 mandates a \$1.50 fee for each new or remanufactured battery sold in the State of Florida.