

<p>PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN: I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED \$100. <input type="checkbox"/> I REQUEST A WRITTEN ESTIMATE. <input type="checkbox"/> I DO NOT REQUEST A WRITTEN ESTIMATE. <input checked="" type="checkbox"/> I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$0.00. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.</p> <p>SIGNED: _____ DATE: 03/26/2022</p>					GUANE GAS STATION GENERAL MECHANIC 1201 NW 7 ST, MIAMI, FL, 33125 Phs: 786-253-0646 MVR: 07110 MV-47286 INVOICE: 7269			____ month/mile warranty on all parts.		
								Intended Payment Method:		
								cash		
								Date: 03/26/2022 Time: 10:31 am		
								Proposed Completion Date:		
Name: MIRIAN					Home Ph:					
Address:					Work Ph:					
City:		State: FL		Zip:		Phone: 7866082503				
Other Authorized Person:					Tag:					
Year/Make: 2007 CHEVROLET		Model: SUBURBAN		Miles In: 0		Miles Out: 0				
VIN#:										
*U/Used R:Rebuilt RC/Reconditioned NC/No Chg/Warranty RD/Reduced/					Save Old Parts: no (Core may apply)					
Qty	Part	Description	Price	Warranty	Complaint/Problem:					
1	3211	ENGINE MOUNT	74.99	2 year	Labor charges based on: hourly rate		Estimate/diagnostic fee: / Or hourly at \$ 0.00 Per hour			
1	2811	TRASMISSION MOUNT	26.87	2 year						
1	3211	ENGINE MOUNT	74.99	2 year						
1	358346	IGNITION WIRES PRO SET	67.94	1 year	A storage fee of \$ 25 per day may be applied to vehicles which are not claimed within 3 working days					
8	41162	SPARK PLUG	12.09	1 year	Description of Repairs (invoice)	Labor	Time	Charges		
1	ETB0024	THOTTLE ASSEMBLY	289.71	2 year	REPLACE ENGINE MOUNT	210	1	PARTS: \$ 968.40		
1	100470	OIL SEAL FRON	29.37	1 year	REPLACE OIL PAN GASKE & FRON SEAL	210	1			
1	OS306993	OIL PAN GASKE SET	69.06	1 year	REPLACE VALVE COVER GASKE & SPARK PLUG	180	1	LABOR: \$ 1,000.00		
1	VS50504R1	VALVE COVER GASKE	34.10	1 year	REPLACE RE MININ SEAL	400	1			
1	CPP1005	VAPOR CAN VENT SOL	88.49	2 year				SUBLET/OTHER: \$ 0.00		
1	635518	REAL MAIN SEAL	69.54	1 year						
1	2134514	COOLER SENSOR	46.62	2 year				SUPPLIES: \$ 0.00		
								FEES: \$ 0.00		
								SUB-TOTAL: \$ 1,968.40		
Estimate good for 30 days. Not responsible for damage caused by theft, fire or acts of nature. I hereby authorize the above repairs, including sublet work, along with the necessary materials. You and your employees may operate my vehicle for the purpose of testing, inspection and delivery at my risk. If I cancel repairs prior to their completion for any reason, a tear down and reassembly fee of \$ 0 will be applied.										
SIGNED: _____ DATE: 03/26/2022					**This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal. ***FS403.718 mandates a \$1.00 fee for each new tire sold in the Sate of Florida. ***FS403.7185 mandates a \$1.50 fee for each new or remanufactured battery sold in the State of Florida.			TOTAL: \$ 2,106.19		